

**Sale Name:** Fall Online Equipment Auction

**LOT 227 - John Deere MX8 8' brush hog, bad gearbox**



### Description

- right side gearbox is bad and needs to be replaced
- 2-pt. hookup with hydraulic adjust offset
- 540 PTO
- hydraulic adjust rear wheels

**Quantity:** 1



<https://www.schneiderauctioneers.com/>